

## Detailed Inventory

Date Last Updated:

10/1/2024

"Purpose of this worksheet: To provide a template for water systems to track materials for each service line in their distribution system.

General Instructions: Each row in this worksheet represents one service line connecting the water main to the customer's plumbing. The columns with the aqua shading are required for the Inventory Summary tab. Note that users can freeze panes to enable them to see the headings and notes when entering data. The worksheet includes examples rows and is formatted for approximately 10,000 entries. Please refer to the red triangle in the upper corner for additional instructions.

Street Address	System-Owned Portion		Customer-Owned Portion	
	Was Material Ever Previously Lead?	Basis of Material Classification	Customer-Owned Portion Service Line Material Classification	Basis of Material Classification
18631 - 41 GALE AVE	No	Field inspection	Non-Lead - Copper	Field inspection
18450 1_4 FARJARDO ST	No	Field inspection	Non-Lead - Plastic	Field inspection
18450 1_4 FARJARDO ST	No	Field inspection	Galvanized	Field inspection
Near 19196 HASTINGS ST ROWLAND HEIGHTS CA - 91748	No	Field inspection	Non-Lead - Other	Field inspection
2432 ABANO AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2429 ABANO AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
2425 ABANO AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
2435 ABANO AVE	No	Field inspection	Galvanized	Field inspection
17847 ABEJA DR	No	Field inspection	Non-Lead - Copper	Field inspection
17846 ABEJA DR	No	Field inspection	Non-Lead - Copper	Field inspection
17842 ABEJA DR	No	Field inspection	Non-Lead - Plastic	Field inspection
17843 ABEJA DR	No	Field inspection	Non-Lead - Plastic	Field inspection
407 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
401 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
411 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
414 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Plastic	Field inspection
419 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
444 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
440 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
434 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
426 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
422 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Plastic	Field inspection
425 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Plastic	Field inspection
433 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Plastic	Field inspection
450 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
510 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
502 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
516 ABELIAN AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Plastic	Field inspection
344 ABERY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
345 ABERY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
340 ABERY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
341 ABERY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
334 ABERY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
335 ABERY AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
328 ABERY AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
329 ABERY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
323 ABERY AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
322 ABERY AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
317 ABERY AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
316 ABERY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
313 ABERY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
310 ABERY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
305 ABERY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
304 ABERY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
300 ABERY AVE	No	Field inspection	Non-Lead - Plastic	Field inspection

































































































































































2016	DESIRE AVE LA PUENTE - 91748	No	Field inspection	Non-Lead - Other	Field inspection
2420	DESIRE AVE ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
1816	DESIRE AVE ROWLAND HEIGHTS - 91748	No	Service line diameter 4 inches or greater	Non-Lead - Other	Field inspection
1835	DESIRE AVE ROWLAND HEIGHTS - 91748	No	Service line diameter 4 inches or greater	Non-Lead - Other	Field inspection
2411	DESIRE AVE, ROWLAND HEIGHTS, CA 91748, USA	No	Field inspection	Galvanized	Field inspection
2411	DESIRE AVE, ROWLAND HEIGHTS, CA 91748, USA	No	Field inspection	Non-Lead - Plastic	Field inspection
1454	DESTOYA AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1448	DESTOYA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1442	DESTOYA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1436	DESTOYA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1430	DESTOYA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1424	DESTOYA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1418	DESTOYA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1404	DESTOYA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1465	DESTOYA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1455	DESTOYA AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1449	DESTOYA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1441	DESTOYA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1435	DESTOYA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1427	DESTOYA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1421	DESTOYA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1417	DESTOYA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1413	DESTOYA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2705	DIONE WAY, ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Copper	Field inspection
2708	DIONE WAY, ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Plastic	Field inspection
2712	DIONE WAY, ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Copper	Field inspection
2714	DIONE WAY, ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Plastic	Field inspection
2713	DIONE WAY, ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Plastic	Field inspection
2709	DIONE WAY, ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Copper	Field inspection
2704	DIONE WAY, ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Plastic	Field inspection
330	DON BAPTISTA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
322	DON BAPTISTA AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
318	DON BAPTISTA AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
323	DON BAPTISTA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
329	DON BAPTISTA AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
319	DON BAPTISTA AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
330	DONNA ANTONIA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
324	DONNA ANTONIA AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
320	DONNA ANTONIA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
316	DONNA ANTONIA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
321	DONNA ANTONIA AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
325	DONNA ANTONIA AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
329	DONNA ANTONIA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2538	DONOSA DR	No	Field inspection	Non-Lead - Copper	Field inspection
2530	DONOSA DR	No	Field inspection	Non-Lead - Copper	Field inspection
2524	DONOSA DR	No	Field inspection	Non-Lead - Copper	Field inspection
2518	DONOSA DR	No	Field inspection	Non-Lead - Copper	Field inspection
2515	DONOSA DR	No	Field inspection	Non-Lead - Copper	Field inspection
2507	DONOSA DR	No	Field inspection	Non-Lead - Copper	Field inspection
2503	DONOSA DR	No	Field inspection	Non-Lead - Copper	Field inspection
2425	DONOSA DR	No	Field inspection	Non-Lead - Copper	Field inspection
2421	DONOSA DR	No	Field inspection	Non-Lead - Copper	Field inspection
2407	DONOSA DR	No	Field inspection	Non-Lead - Copper	Field inspection
2400	DONOSA DR	No	Field inspection	Non-Lead - Copper	Field inspection
2412	DONOSA DR	No	Field inspection	Non-Lead - Plastic	Field inspection
2380	DONOSA DR	No	Field inspection	Non-Lead - Plastic	Field inspection
2368	DONOSA DR	No	Field inspection	Non-Lead - Copper	Field inspection
2347	DONOSA DR	No	Field inspection	Non-Lead - Copper	Field inspection
2413	DONOSA DR	No	Field inspection	Non-Lead - Plastic	Field inspection



























































2804	FULLERTON RD	No	Field inspection	Non-Lead - Other	Field inspection
2720	FULLERTON RD	No	Field inspection	Non-Lead - Plastic	Field inspection
2704	FULLERTON RD	No	Field inspection	Non-Lead - Plastic	Field inspection
2664	FULLERTON RD	No	Field inspection	Non-Lead - Copper	Field inspection
1900	FULLERTON RD	No	Service line diameter 4 inches or greater	Non-Lead - Other	Service line diameter 4 inches or greater
1900	FULLERTON RD	No	Field inspection	Non-Lead - Other	Service line diameter 4 inches or greater
1940	FULLERTON RD	No	Service line diameter 4 inches or greater	Non-Lead - Other	Field inspection
1940	FULLERTON RD	No	Service line diameter 4 inches or greater	Non-Lead - Other	Service line diameter 4 inches or greater
1199	FULLERTON RD	No	Field inspection	Non-Lead - Plastic	Field inspection
2161	FULLERTON RD	No	Field inspection	Non-Lead - Plastic	Field inspection
1199	FULLERTON RD	No	Field inspection	Non-Lead - Copper	Field inspection
	FULLERTON RD	No	Field inspection	Non-Lead - Other	Field inspection
2804	FULLERTON RD - FS	No	Field inspection	Non-Lead - Other	Field inspection
1081	FULLERTON RD - FS	No	Field inspection	Non-Lead - Other	Field inspection
1210	FULLERTON RD - FS	No	Field inspection	Non-Lead - Other	Field inspection
2740	FULLERTON RD - FS	No	Field inspection	Non-Lead - Other	Field inspection
1110	FULLERTON RD - FS	No	Field inspection	Non-Lead - Other	Field inspection
2632	FULLERTON RD - FS	No	Field inspection	Non-Lead - Other	Field inspection
1940	FULLERTON RD - FS	No	Field inspection	Non-Lead - Other	Field inspection
2628	FULLERTON RD - FS	No	Field inspection	Non-Lead - Other	Field inspection
1101	FULLERTON RD - FS	No	Field inspection	Non-Lead - Other	Field inspection
1121	FULLERTON RD - FS	No	Field inspection	Non-Lead - Other	Field inspection
1390	FULLERTON RD - FS	No	Field inspection	Non-Lead - Other	Field inspection
1330	FULLERTON RD - FS	No	Field inspection	Non-Lead - Other	Field inspection
2161	FULLERTON RD - FS	No	Field inspection	Non-Lead - Other	Field inspection
1751	FULLERTON RD #1	No	Field inspection	Non-Lead - Plastic	Field inspection
2251	FULLERTON RD #10A	No	Field inspection	Non-Lead - Copper	Field inspection
2251	FULLERTON RD #10A	No	Field inspection	Non-Lead - Plastic	Field inspection
1767	FULLERTON RD #2	No	Field inspection	Non-Lead - Plastic	Field inspection
1757	FULLERTON RD #4	No	Field inspection	Non-Lead - Plastic	Field inspection
1380	FULLERTON RD INDUSTRY - 91748	No	Field inspection	Non-Lead - Other	Field inspection
1380	FULLERTON RD INDUSTRY - 91748	No	Field inspection	Non-Lead - Other	Field inspection
1110	FULLERTON RD INDUSTRY - 91748	No	Field inspection	Non-Lead - Other	Field inspection
1250	FULLERTON RD INDUSTRY - 91748	No	Field inspection	Non-Lead - Other	Field inspection
1250	FULLERTON RD INDUSTRY - 91748	No	Field inspection	Non-Lead - Other	Field inspection
2840	FULLERTON RD ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
2508	FULLERTON RD, ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Copper	Field inspection
2110	FULLERTON RD, ROWLAND HEIGHTS, CA 91748, USA	No	Field inspection	Non-Lead - Plastic	Field inspection
2740	FULLERTON RD, ROWLAND HEIGHTS, CA 91748, USA	No	Field inspection	Non-Lead - Copper	Field inspection
2740	FULLERTON RD, ROWLAND HEIGHTS, CALIFORNIA 91748, UNITED STATES	No	Field inspection	Non-Lead - Copper	Field inspection
18233	GALATINA ST	No	Field inspection	Non-Lead - Copper	Field inspection
18227	GALATINA ST	No	Field inspection	Non-Lead - Copper	Field inspection
18221	GALATINA ST	No	Field inspection	Non-Lead - Copper	Field inspection
18213	GALATINA ST	No	Field inspection	Non-Lead - Copper	Field inspection
18207	GALATINA ST	No	Field inspection	Non-Lead - Copper	Field inspection
18202	GALATINA ST	No	Field inspection	Non-Lead - Copper	Field inspection
18208	GALATINA ST	No	Field inspection	Non-Lead - Copper	Field inspection
18214	GALATINA ST	No	Field inspection	Non-Lead - Copper	Field inspection
18220	GALATINA ST	No	Field inspection	Non-Lead - Copper	Field inspection
18226	GALATINA ST	No	Field inspection	Non-Lead - Copper	Field inspection
18232	GALATINA ST	No	Field inspection	Non-Lead - Copper	Field inspection
18007	GALATINA ST	No	Field inspection	Non-Lead - Copper	Field inspection
18013	GALATINA ST	No	Field inspection	Non-Lead - Plastic	Field inspection
18017	GALATINA ST	No	Field inspection	Non-Lead - Plastic	Field inspection
18003	GALATINA ST	No	Field inspection	Non-Lead - Copper	Field inspection
18021	GALATINA ST	No	Field inspection	Non-Lead - Plastic	Field inspection
18047	GALATINA ST	No	Field inspection	Non-Lead - Copper	Field inspection
18064	GALATINA ST ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
18043	GALATINA ST ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection



















































18416	HURLEY ST	No	Field inspection	Non-Lead - Plastic	Field inspection
18516	HURLEY ST	No	Field inspection	Non-Lead - Copper	Field inspection
18510	HURLEY ST	No	Field inspection	Non-Lead - Plastic	Field inspection
18521	HURLEY ST	No	Field inspection	Non-Lead - Copper	Field inspection
18504	HURLEY ST	No	Field inspection	Non-Lead - Plastic	Field inspection
18440	HURLEY ST	No	Field inspection	Non-Lead - Copper	Field inspection
18515	HURLEY ST	No	Field inspection	Non-Lead - Copper	Field inspection
18434	HURLEY ST	No	Field inspection	Non-Lead - Plastic	Field inspection
18509	HURLEY ST	No	Field inspection	Non-Lead - Copper	Field inspection
18428	HURLEY ST	No	Field inspection	Non-Lead - Copper	Field inspection
18503	HURLEY ST	No	Field inspection	Non-Lead - Copper	Field inspection
18422	HURLEY ST	No	Field inspection	Non-Lead - Copper	Field inspection
18439	HURLEY ST	No	Field inspection	Non-Lead - Copper	Field inspection
18410	HURLEY ST	No	Field inspection	Non-Lead - Copper	Field inspection
18404	HURLEY ST	No	Field inspection	Non-Lead - Copper	Field inspection
18433	HURLEY ST	No	Field inspection	Non-Lead - Plastic	Field inspection
18427	HURLEY ST	No	Field inspection	Non-Lead - Plastic	Field inspection
18415	HURLEY ST	No	Field inspection	Non-Lead - Copper	Field inspection
18421	HURLEY ST	No	Field inspection	Non-Lead - Plastic	Field inspection
18403	HURLEY ST	No	Field inspection	Non-Lead - Plastic	Field inspection
18527	HURLEY ST	No	Field inspection	Non-Lead - Plastic	Field inspection
19201	IVORY WAY, ROWLAND HEIGHTS - 91748	No	Field inspection	Galvanized	Field inspection
19203	IVORY WAY, ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Copper	Field inspection
19205	IVORY WAY, ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Copper	Field inspection
19208	IVORY WAY, ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Plastic	Field inspection
19204	IVORY WAY, ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Copper	Field inspection
19200	IVORY WAY, ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Copper	Field inspection
18064	JEANNIE DR	No	Field inspection	Non-Lead - Copper	Field inspection
18072	JEANNIE DR	No	Field inspection	Non-Lead - Plastic	Field inspection
18075	JEANNIE DR	No	Field inspection	Non-Lead - Copper	Field inspection
18063	JEANNIE DR	No	Field inspection	Non-Lead - Copper	Field inspection
18003	JEANNIE DR	No	Field inspection	Non-Lead - Copper	Field inspection
18018	JEANNIE DR	No	Field inspection	Non-Lead - Copper	Field inspection
18010	JEANNIE DR	No	Field inspection	Non-Lead - Copper	Field inspection
18004	JEANNIE DR	No	Field inspection	Non-Lead - Copper	Field inspection
18009	JEANNIE DR LA PUENTE - 91744	No	Field inspection	Non-Lead - Other	Field inspection
1175	JELLY AVE	No	Field inspection	Non-Lead - Other	Field inspection
1400	JELLY AVE	No	Service line diameter 4 inches or greater	Non-Lead - Other	Field inspection
1177	JELLY AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1115	JELLY AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1100	JELLY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1177	JELLY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
650	JELLY AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
646	JELLY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
642	JELLY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
638	JELLY AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
602	JELLY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
632	JELLY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
626	JELLY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
608	JELLY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
620	JELLY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
614	JELLY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
569	JELLY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
563	JELLY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
557	JELLY AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
551	JELLY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
545	JELLY AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
539	JELLY AVE	No	Field inspection	Non-Lead - Copper	Field inspection
533	JELLY AVE	No	Field inspection	Non-Lead - Copper	Field inspection



1777	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1902	JELLYCK AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
2103	JELLYCK AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1908	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1803	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2109	JELLYCK AVE	No	Field inspection	Galvanized	Field inspection
1916	JELLYCK AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1809	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2121	JELLYCK AVE	No	Field inspection	Galvanized	Field inspection
2115	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1905	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1835	JELLYCK AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1817	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2139	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2145	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1829	JELLYCK AVE	No	Field inspection	Galvanized	Field inspection
2151	JELLYCK AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1823	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2157	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2133	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2163	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1928	JELLYCK AVE	No	Field inspection	Galvanized	Field inspection
1931	JELLYCK AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
2164	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1936	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2144	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1937	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2140	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2134	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1943	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1949	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1967	JELLYCK AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1961	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2003	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2110	JELLYCK AVE	No	Field inspection	Galvanized	Field inspection
2009	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2015	JELLYCK AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
2100	JELLYCK AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
2014	JELLYCK AVE	No	Field inspection	Galvanized	Field inspection
2021	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2008	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2034	JELLYCK AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1917	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2053	JELLYCK AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1411	JELLYCK AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
435	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
538	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1955	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2162	JELLYCK AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1413	JELLYCK AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1111	JELLYCK AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
1423	JELLYCK AVE #D	No	Field inspection	Non-Lead - Plastic	Field inspection
410	JELLYCK AVE LA PUENTE - 91744	No	Field inspection	Non-Lead - Other	Field inspection
2127	JELLYCK AVE LA PUENTE - 91748	No	Field inspection	Non-Lead - Other	Field inspection
1345	JELLYCK AVE LA PUENTE - 91748	No	Field inspection	Non-Lead - Other	Field inspection
1922	JELLYCK AVE LA PUENTE - 91748	No	Field inspection	Non-Lead - Other	Field inspection
1925	JELLYCK AVE LA PUENTE - 91748	No	Field inspection	Non-Lead - Other	Field inspection
1911	JELLYCK AVE ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
1400	JELLYCK AVE, ROWLAND HEIGHTS, CA 91748, USA	No	Field inspection	Non-Lead - Copper	Field inspection

















441	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
435	LA SEDA RD	No	Field inspection	Non-Lead - Plastic	Field inspection
427	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
415	LA SEDA RD	No	Field inspection	Galvanized	Field inspection
421	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
440	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
446	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
452	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
458	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
464	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
470	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
502	LA SEDA RD	No	Field inspection	Non-Lead - Plastic	Field inspection
506	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
526	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
530	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
536	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
542	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
554	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
548	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
566	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
572	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
569	LA SEDA RD	No	Field inspection	Non-Lead - Plastic	Field inspection
603	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
575	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
615	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
621	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
627	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
633	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
639	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
645	LA SEDA RD	No	Field inspection	Non-Lead - Plastic	Field inspection
651	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
609	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
616	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
622	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
610	LA SEDA RD	No	Field inspection	Non-Lead - Plastic	Field inspection
515	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
514	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
521	LA SEDA RD	No	Field inspection	Non-Lead - Plastic	Field inspection
459	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
453	LA SEDA RD	No	Field inspection	Non-Lead - Plastic	Field inspection
560	LA SEDA RD	No	Field inspection	Non-Lead - Plastic	Field inspection
341	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
341	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
341	LA SEDA RD	No	Field inspection	Non-Lead - Copper	Field inspection
650	LA SEDA RD LA PUENTE - 91744	No	Service line diameter 4 inches or greater	Non-Lead - Other	Field inspection
626	LA SEDA RD LA PUENTE - 91744	No	Service line diameter 4 inches or greater	Non-Lead - Other	Field inspection
18888	LABIN CT	No	Field inspection	Non-Lead - Copper	Field inspection
18888	LABIN CT	No	Field inspection	Non-Lead - Copper	Field inspection
18888	LABIN CT	No	Field inspection	Non-Lead - Copper	Field inspection
18888	LABIN CT	No	Field inspection	Non-Lead - Copper	Field inspection
18888	LABIN CT	No	Field inspection	Non-Lead - Copper	Field inspection
18888	LABIN CT	No	Field inspection	Non-Lead - Copper	Field inspection
18963	LABIN CT	No	Field inspection	Non-Lead - Plastic	Field inspection
18970	LABIN CT	No	Field inspection	Non-Lead - Copper	Field inspection
18970	LABIN CT	No	Field inspection	Non-Lead - Plastic	Field inspection
18888	LABIN CT - FS	No	Field inspection	Non-Lead - Other	Field inspection
18970	LABIN CT - FS	No	Field inspection	Non-Lead - Other	Field inspection
18366	LANACA ST	No	Field inspection	Non-Lead - Plastic	Field inspection
18360	LANACA ST	No	Field inspection	Non-Lead - Copper	Field inspection



















































































2238	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2108	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1976	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2244	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2250	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2102	PASO REAL AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
2256	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2040	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2262	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2034	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2270	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2028	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2024	PASO REAL AVE	No	Field inspection	Galvanized	Field inspection
2012	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2018	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2004	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1964	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1952	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1958	PASO REAL AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1946	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1936	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1930	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1940	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1924	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1918	PASO REAL AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1912	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1844	PASO REAL AVE	No	Field inspection	Galvanized	Field inspection
1838	PASO REAL AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1802	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1832	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1820	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1814	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1820	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1808	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1731	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1775	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1850	PASO REAL AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1924	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2135	PASO REAL AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
2146	PASO REAL AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1441	PASO REAL AVE	No	Field inspection	Galvanized	Field inspection
18150	PATHFINDER RD	No	Field inspection	Non-Lead - Other	Field inspection
18150	PATHFINDER RD	No	Field inspection	Non-Lead - Plastic	Field inspection
19351	PATHFINDER RD	No	Field inspection	Non-Lead - Copper	Field inspection
18150	PATHFINDER RD - FS	No	Field inspection	Non-Lead - Other	Field inspection
	PATHFINDER RD - FS	No	Field inspection	Non-Lead - Other	Field inspection
18150	PATHFINDER RD - FS1	No	Field inspection	Non-Lead - Other	Field inspection
18150	PATHFINDER RD #2	No	Service line diameter 4 inches or greater	Non-Lead - Other	Field inspection
80A	PATHFINDER ROAD, ROWLAND HEIGHTS, CALIFORNIA 91748, UNITED STATES	No	Field inspection	Non-Lead - Plastic	Field inspection
2474A	PATRICIAN VIEW, ROWLAND HEIGHTS, CALIFORNIA 91748, UNITED STATES	No	Field inspection	Non-Lead - Copper	Field inspection
1825	PAVAS CT	No	Field inspection	Non-Lead - Copper	Field inspection
1815	PAVAS CT	No	Field inspection	Non-Lead - Copper	Field inspection
1805	PAVAS CT	No	Field inspection	Non-Lead - Plastic	Field inspection
1800	PAVAS CT	No	Field inspection	Non-Lead - Copper	Field inspection
1810	PAVAS CT	No	Field inspection	Non-Lead - Copper	Field inspection
1820	PAVAS CT	No	Field inspection	Non-Lead - Other	Field inspection
1830	PAVAS CT	No	Field inspection	Non-Lead - Other	Field inspection
1840	PAVAS CT	No	Field inspection	Non-Lead - Plastic	Field inspection
1850	PAVAS CT	No	Field inspection	Non-Lead - Other	Field inspection















17445	RAILROAD ST	No	Field inspection	Non-Lead - Plastic	Field inspection
17448	RAILROAD ST	No	Field inspection	Non-Lead - Copper	Field inspection
17448	RAILROAD ST	No	Field inspection	Non-Lead - Plastic	Field inspection
17611	RAILROAD ST	No	Field inspection	Non-Lead - Copper	Field inspection
17232	RAILROAD ST	No	Field inspection	Non-Lead - Copper	Field inspection
17380	RAILROAD ST	No	Service line diameter 4 inches or greater	Non-Lead - Other	Service line diameter 4 inches or greater
17625	RAILROAD ST - FS	No	Field inspection	Non-Lead - Other	Field inspection
17769	RAILROAD ST - FS	No	Field inspection	Non-Lead - Other	Field inspection
17721	RAILROAD ST - FS	No	Field inspection	Non-Lead - Other	Field inspection
18001	RAILROAD ST - FS	No	Field inspection	Non-Lead - Other	Field inspection
17579	RAILROAD ST - FS	No	Field inspection	Non-Lead - Other	Field inspection
17915	RAILROAD ST - FS	No	Field inspection	Non-Lead - Other	Field inspection
17651	RAILROAD ST - FS	No	Field inspection	Non-Lead - Other	Field inspection
17969	RAILROAD ST - FS	No	Field inspection	Non-Lead - Other	Field inspection
17521	RAILROAD ST - FS	No	Field inspection	Non-Lead - Other	Field inspection
18111	RAILROAD ST - FS	No	Field inspection	Non-Lead - Other	Field inspection
17851	RAILROAD ST - FS	No	Field inspection	Non-Lead - Other	Field inspection
17851	RAILROAD ST - FS1	No	Field inspection	Non-Lead - Other	Field inspection
17231	RAILROAD ST #200	No	Field inspection	Non-Lead - Copper	Field inspection
17448	RAILROAD ST INDUSTRY - 91748	No	Field inspection	Non-Lead - Other	Field inspection
18217	RAILROAD ST INDUSTRY - 91748	No	Field inspection	Non-Lead - Other	Field inspection
17851	RAILROAD ST INDUSTRY - 91748	No	Field inspection	Non-Lead - Other	Field inspection
18217	RAILROAD ST INDUSTRY - 91748	No	Field inspection	Non-Lead - Other	Field inspection
17851	RAILROAD ST INDUSTRY - 91748	No	Field inspection	Non-Lead - Other	Field inspection
17445	RAILROAD ST INDUSTRY - 91748	No	Field inspection	Non-Lead - Other	Field inspection
17448	RAILROAD ST INDUSTRY - 91748	No	Field inspection	Non-Lead - Other	Field inspection
17380	RAILROAD ST INDUSTRY - 91748	No	Service line diameter 4 inches or greater	Non-Lead - Other	Field inspection
18383	RAILROAD ST INDUSTRY - 91748	No	Service line diameter 4 inches or greater	Non-Lead - Other	Field inspection
17355	RAILROAD ST LA PUENTE - 91748	No	Service line diameter 4 inches or greater	Non-Lead - Other	Field inspection
17355	RAILROAD ST LA PUENTE - 91748	No	Service line diameter 4 inches or greater	Non-Lead - Other	Field inspection
17735-47	RAILROAD ST*	No	Field inspection	Non-Lead - Other	Field inspection
17851	RAILROAD ST, CITY OF INDUSTRY, CA - 91748	No	Field inspection	Non-Lead - Copper	Field inspection
2340	RAINER AVE	No	Field inspection	Galvanized	Field inspection
2324	RAINER AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
2320	RAINER AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2312	RAINER AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
2316	RAINER AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
2308	RAINER AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
2300	RAINER AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2305	RAINER AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2321	RAINER AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
2329	RAINER AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
2339	RAINER AVE	No	Field inspection	Non-Lead - Copper	Field inspection
2311	RAINER AVE ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
2317	RAINER AVE ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
2325	RAINER AVE ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
2304	RAINER AVE ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
2333	RAINER AVE ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
2301	RAINER AVE ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
16324	RANMORE DR, HACIENDA HEIGHTS - 91745	No	Field inspection	Non-Lead - Copper	Field inspection
16312	RANMORE DR, HACIENDA HEIGHTS - 91745	No	Field inspection	Non-Lead - Copper	Field inspection
16306	RANMORE DR, HACIENDA HEIGHTS - 91745	No	Field inspection	Non-Lead - Copper	Field inspection
16303	RANMORE DR, HACIENDA HEIGHTS - 91745	No	Field inspection	Non-Lead - Copper	Field inspection
16309	RANMORE DR, HACIENDA HEIGHTS - 91745	No	Field inspection	Non-Lead - Plastic	Field inspection
16315	RANMORE DR, HACIENDA HEIGHTS - 91745	No	Field inspection	Non-Lead - Copper	Field inspection
16372	RANMORE DR, HACIENDA HEIGHTS - 91745	No	Field inspection	Non-Lead - Copper	Field inspection
16321	RANMORE DR, HACIENDA HEIGHTS - 91745	No	Field inspection	Non-Lead - Other	Field inspection
16327	RANMORE DR, HACIENDA HEIGHTS - 91745	No	Field inspection	Non-Lead - Copper	Field inspection
16364	RANMORE DR, HACIENDA HEIGHTS - 91745	No	Field inspection	Non-Lead - Copper	Field inspection































1629	S AZUSA AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1697	S AZUSA AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
1697	S AZUSA AVE	No	Field inspection	Non-Lead - Other	Field inspection
1548	S AZUSA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1548	S AZUSA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1850	S AZUSA AVE	No	Field inspection	Non-Lead - Other	Field inspection
1905	S AZUSA AVE	No	Field inspection	Non-Lead - Other	Field inspection
1905	S AZUSA AVE	No	Field inspection	Non-Lead - Other	Field inspection
1905	S AZUSA AVE	No	Field inspection	Non-Lead - Other	Field inspection
1548	S AZUSA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1420	S AZUSA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1901	S AZUSA AVE	No	Service line diameter 4 inches or greater	Non-Lead - Other	Service line diameter 4 inches or greater
1901	S AZUSA AVE	No	Service line diameter 4 inches or greater	Non-Lead - Other	Service line diameter 4 inches or greater
881	S AZUSA AVE	No	Service line diameter 4 inches or greater	Non-Lead - Other	Service line diameter 4 inches or greater
881	S AZUSA AVE	No	Field inspection	Non-Lead - Other	Service line diameter 4 inches or greater
877	S AZUSA AVE	No	Field inspection	Non-Lead - Plastic	Field inspection
885	S AZUSA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
885	S AZUSA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1548	S AZUSA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1548	S AZUSA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1548	S AZUSA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1600	S AZUSA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
1655	S AZUSA AVE	No	Field inspection	Non-Lead - Copper	Field inspection
881	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
1478	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
1590	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
1548	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
1542	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
1655	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
883	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
1480	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
1418	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
1697	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
1420	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
888	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
887	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
1015	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
1850	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
1625	S AZUSA AVE - FS	No	Field inspection	Non-Lead - Other	Field inspection
880	S AZUSA AVE - FS1	No	Field inspection	Non-Lead - Other	Field inspection
1905	S AZUSA AVE HACIENDA HEIGHTS - 91745	No	Field inspection	Non-Lead - Other	Field inspection
1901	S AZUSA AVE HACIENDA HEIGHTS - 91745	No	Field inspection	Non-Lead - Other	Field inspection
500	S AZUSA AVE INDUSTRY - 91744	No	Field inspection	Non-Lead - Other	Field inspection
1560	S AZUSA AVE INDUSTRY - 91748	No	Field inspection	Non-Lead - Other	Field inspection
1548	S AZUSA AVE INDUSTRY - 91748	No	Field inspection	Non-Lead - Other	Field inspection
1630	S AZUSA AVE INDUSTRY - 91748	No	Field inspection	Non-Lead - Other	Field inspection
1560	S AZUSA AVE INDUSTRY - 91748	No	Service line diameter 4 inches or greater	Non-Lead - Other	Field inspection
885	S AZUSA AVE INDUSTRY - 91748	No	Service line diameter 4 inches or greater	Non-Lead - Other	Field inspection
3981-3869	S BREA CANYON RD, DIAMOND BAR, CA 91765, USA	No	Field inspection	Non-Lead - Copper	Field inspection
501	S DARNEY AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
507	S DARNEY AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
513	S DARNEY AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
520	S DARNEY AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
528	S DARNEY AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
521	S DARNEY AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
525	S DARNEY AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
534	S DARNEY AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Other	Field inspection
533	S DARNEY AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection
537	S DARNEY AVE, WEST COVINA - 91792	No	Field inspection	Non-Lead - Copper	Field inspection































































































3000	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3048	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3003	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3130	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3027	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3135	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3107	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3036	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3018	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3043	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3010	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3125	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3002	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3035	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3102	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3019	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3011	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3117	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection
3116	YORKSHIRE WAY ROWLAND HEIGHTS - 91748	No	Field inspection	Non-Lead - Other	Field inspection